Notice

SANYO
IIIII

CORRECTION PRODUCTION CH	
SERVICE FLASH ADD INFORMATI	
Please add this notice to the Service Manual list	ted below. REVISION 6
Category: COLOR TELEVISION	Date: October / 18 / 2007
Model:	Effective from : Chassis No. P32647-06

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P32647-03. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P32647-03 used in Model DP32647 (SM780145).

REF. No. SM780145-06

Servicing should be performed by only trained and qualified service personnel.

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

Destination: U.S.A. / CANADA

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
C5722	C5722	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
	00722	New	N/A	NOT USED	0	NO	
	Page 11 C5724 Chassis	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
		New	N/A	NOT USED	0	NO	
Parts List C5725	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D	
	03723	New	N/A	NOT USED	0	NO	D
C5	C5726	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
	00,20	New	N/A	NOT USED	0	NO	

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
	C5727	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
	03727	New	N/A	NOT USED	0	NO	
	C5728	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
Page 11 Chassis Electrical		New	N/A	NOT USED	0	NO	
Parts List	05700	Old	CK1H104ZLZFNG	CERAMIC 0.1U Z 50V	1	NO	D
	C5729	New	N/A	NOT USED	0	NO	
	105700	Old	QXXAVC524M	1C EDD1216AATA-6B-E	1	NO	D
	IC5700	New	QXXAVC926M	1C EDD2516AETA-5B-E	1	NO	
	105700	Old	QXXAVC524M	1C EDD1216AATA-6B-E	1	NO	D
Page 13 Chassis	IC5720	New	N/A	NOT USED	0	NO	
Electrical Parts List	DDEEZO	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
	RB5578	New	N/A	NOT USED	0	NO	
	RB5579	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	D
	מסטוש	New	N/A	NOT USED	0	NO	
	DDCC00	Old	1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	
Page 18 Chassis Electrical	RB5580	New	N/A	NOT USED	0	NO	D
Parts List	DDCC04		1AV4R1D31504G	R-NETWORK 15X4 1/32W	1	NO	
	RB5581	New	N/A	NOT USED	0	NO	D
	DE 570	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
	R5578	New	N/A	NOT USED	0	NO	
Page 21 Chassis	R5579	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
Electrical Parts List	R5580	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	

1. IN THE CHASSIS ELECTRICAL PARTS LIST MAIN PC BOARD AND MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
	R5581	Old	RGF15R0JTCANL	MT-GLAZE 15 JA 1/10W	1	NO	D
Page 21 Chassis	113301	New	N/A	NOT USED	0	NO	ט
Electrical Parts List	Electrical	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	RGF1200FTCANL	MT-GLAZE 120 FA 1/10W	1	NO	
Page 23 Chassis Electrical Parts List	 \$\D\\$\D\\$\D\\$\D\\$\D\\$\D\\$\D\\$\D\\$\D\\$\D	Old	1AV4U20C09800	UNIT, INVERTER-POWER	1	NO	D
		New	1AV4U20C17200	UNIT, INVERTER-POWER	1	NO	

For parts or service contact

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

September 2007 SMC Published in U.S.A.